

Tamarind survived the storm with typical wind damage. Aluminum Shingles blown off and lawn debris. Some reports of water infiltration and we will attempt to find source and make repairs as soon as possible. Still no power in Englewood and the Key which makes life challenging in regards to moving forward. We are blessed to say the least.

Ron